

FIG. 1






FIG. 2



209020 69599001 1006559.020602

FIG. 3



209020-6959900T

10066569-020600

FIG. 4




FIG. 5





FIG. 6



10066569.020602

FIG. 7





FIG. 8



20250206 09:02:00

FIG. 9





FIG. 10A


PEN OPERATION MODE		OUTPUT COORDINATE MODE	PEN TIP SW 41	SW1 42_a	SW2 42_b	DRIVING MODE		COORDINATE CALCULATION VALUE IN Z-AXIS DIRECTION
PEN INPUT OPERATION	PEN DOWN	ABSOLUTE COORDINATES	ON	—	—	1(50p/sec)	2(40p/sec)	(300mm OR LESS)
						<input type="radio"/>		
PROXIMITY INPUT OPERATION	PEN UP	ABSOLUTE COORDINATES	OFF	ON	OFF		<input type="radio"/>	300mm OR LESS
	PEN UP	ABSOLUTE COORDINATES	OFF	OFF	ON		<input type="radio"/>	300mm OR LESS
	PEN DOWN	ABSOLUTE COORDINATES	OFF	ON	ON	<input type="radio"/>		300mm OR LESS
	PEN UP	RELATIVE COORDINATES	OFF	ON	OFF		<input type="radio"/>	1000mm OR MORE
REMOTE INPUT OPERATION	PEN UP	RELATIVE COORDINATES	OFF	OFF	ON		<input type="radio"/>	1000mm OR MORE
	PEN DOWN	RELATIVE COORDINATES	OFF	ON	ON	<input type="radio"/>		1000mm OR MORE

FIG. 10B



1006559-020602

FIG. 11



10065569.020602

FIG. 12





FIG. 13



10066563.020602